



Glenmore Trail East Interchanges Functional Planning Study

Appendix H - Road Safety Audit Report


Prepared By:





PARSONS

Glenmore Trail: 100 Street SE to Rainbow Road Road Safety Audit





McElhanney Consulting Services Ltd. 500, 999 – 8th Street SW Calgary AB T2R 1J5 Contact: Cory Wilson Phone [403-776-9675] Email: cwilson@mcelhanney.com

2511-00527-00

OQM Organizational Quality



Glenmore Trail - 100 Street SE to Rainbow Road Interchange Functional Plan Road Safety Audit

Prepared By:

STHOLENGING TO SSSHORE STATES SSHORE SSHORE STATES SSHORE SSHORE SSHORE STATES SSHORE SSHORE

Aparna Krishan, P.Eng. Transportation Engineer Reviewed By:



Cory Wilson, P.Eng. Senior Transportation Engineer

This report was prepared by McElhanney Consulting Services Ltd. ("McElhanney") for the exclusive use of the Client identified in this report (the "Client") and may not be reproduced, used or relied upon, in whole or in part, by a party other than the Client, without the prior written consent of McElhanney. Any unauthorized use, reliance and/or decisions made based on the information contained within this report are at the sole risk of such parties. This is a technical report and is not a legal representation or interpretation of environmental laws, rules, regulations, or policies of governmental agencies.

Table of Contents

1.	Introduction1				
2.	Road	d Safety Audit Process	2		
2	2.1.	Audit Team	2		
2	2.2.	Risk Assessment	2		
2	2.3.	Scope of Audit	3		
3.	Dive	rging Diamond Interchange	3		
4.	Audi	t Findings	4		
2	.1.	Safety Benefits	4		
2	.2.	Summary of Potential Safety Issues Identified	5		
Z	4.3. Potential Safety Issues				
5.	Assu	umptions / Considerations	20		
6.	Cond	clusion	20		
Ap	Appendix A – Interchange Plan and Profile Drawing Package21				

Tables

Table 1: Risk Assessment Matrix	3
Table 2: Summary of Potential Safety Issues	5

Figures

Figure	 Study Are 	ea	1
. igai o	n etaay / a	~	•••

1. Introduction

McElhanney Consulting Services Ltd. (MCSL) was retained by Parsons Corporation (Parsons) to carry out a Road Safety Audit (RSA) of an interchange functional plan for three intersections along Glenmore Trail in Southeast Calgary.

The study area, as shown in Figure 1, includes proposed interchanges on Glenmore Trail at 100 Street SE (Garden Road), Conrich Road (Range Road 284), and Rainbow Road (Range Road 283).



Source: Google Earth Image

Figure 1: Study Area

MCSL has conducted an RSA of the proposed plans for the study area. The RSA was conducted in accordance with the Transportation Association of Canada's (TAC) <u>The Canadian Road Safety Audit Guide</u> (2001) for the area under review to identify deficiencies that should be mitigated prior to finalization of the designs. The potential safety issues identified in this report are based on the Functional Planning Study Plan and Profile drawing package prepared by Parsons and received by McElhanney on July 19, 2017 (included as Appendix A). The findings of the audit are documented in this report.



2. Road Safety Audit Process

A road safety audit is a formal evaluation of the safety performance of an existing or future road, intersection, or interchange by an audit team. Road safety audits help to promote road safety by identifying safety issues at the design and implementation stages, promoting awareness of safe design practices, integrating multimodal safety concerns, and considering human factors in the design.

The safety audit was conducted based on the functional planning design drawings, and the identified safety issues and mitigation suggestions have been developed with consideration for the type of improvements that are feasible at the current design stage. The purpose of the RSA is not to review the validity of design concepts, nor to be a design standards check. Rather the intent is to identify and quantify potential safety and collision risks and suggest potential improvements.

The audit team has conducted this audit to the best of its professional abilities. While every attempt has been made to identify significant safety issues, the project owner is reminded that no road is immune to the occurrence of collisions. In addition to the road characteristics, there are other factors, such as driver behaviour and adverse weather that are outside the control of the design team that may contribute to a collision. The purpose of this audit is to identify potential safety issues related to the road design and recommend improvement options to reduce the risk of collisions. The design team and project owner are reminded that the responsibility for the design, construction, and performance of the project remains with the engineers of record.

2.1. Audit Team

According to the Transportation Association of Canada's (TAC) <u>Canadian Guide to In-Service Road Safety</u> <u>Reviews</u> (2004), a Road Safety Audit is a "formal and independent safety performance review". Road Safety Audits are considered independent because the individuals that conduct the audit are typically detached from the project team undertaking the design. The Road Safety Auditors were not involved in any stage of the roadway planning or design.

2.2. Risk Assessment

A collision risk assessment was carried out for each identified safety issue. The expected frequency and severity of collisions related to each potential safety issue was evaluated and rated according to the categories noted in Table 1. The two risk elements of frequency and severity were then combined to obtain a risk assessment rating. In this way, safety issues were assigned a ranking between F (highest risk and highest priority) and A (lowest risk and lowest priority).

The frequency and severity assessments for each issue evaluated are based on engineering judgment and are therefore subjective. However, the risk assessment still provides a useful tool for prioritizing risk mitigation and safety improvement recommendations.



Expected	Expected Severity			
Frequency	Property Damage Only	Minor Injury	Major Injury	Fatal
> 5 per year	С	D	E	F
1 – 4 per year	В	С	D	E
< 1 per year, > 1 per 5 years	A	В	С	D
< 1 per 5 years	A	A	В	с

Table 1: Risk Assessment Matrix

For each safety issue identified, possible mitigation measures have been suggested. The suggestions focus on actions and measures that can be incorporated into the proposed designs and drawings, or otherwise cost-effectively implemented at the detailed design stage.

2.3. Scope of Audit

The scope of this audit was to review the plan and profile drawings included in the package received from Parsons titled "Functional Planning Study Glenmore Trail East – Stoney Tr to Rainbow Rd (Range Road 283)." This included the proposed designs of the diverging diamond interchanges at the intersections of Glenmore Trail SE with 100 Street SE (basket weave and non-basket weave options), Conrich Road, and Rainbow Road. The drawing elements reviewed included the geometric design, alignment, and roadway configuration proposed for the new diverging diamond interchanges.

It should be noted that at this stage, the plans were not sufficiently detailed to allow a review of elements such as pavement markings, signage, and illumination.

3. Diverging Diamond Interchange

Diverging diamond interchanges are proposed for construction at the intersections of Glenmore Trail SE with 100 Street SE, Conrich Road, and Rainbow Road. The diverging diamond interchange design involves allowing traffic movements to cross-over from driving on the right-hand side of the road to the left side on the interchange approach in advance of the intersecting roadway, such that left turn movements can be made as free-flow movements without conflicts with opposing traffic. A second cross-over point then switches the roadway configuration back to standard right-side driving after traversing the intersection.



This is a relatively new type of interchange in both Canada and in Calgary, with the first such interchange opening in Calgary on August 14, 2017. As with any new infrastructure design, there is a risk of issues associated with user unfamiliarity and reduced driver comfort levels. These risks are expected to reduce over time and have not been identified as a specific issue in the audit. Suggestions have been made to help provide positive guidance through the interchange and to reduce any risks that may be associated with driver unfamiliarity.

4. Audit Findings

4.1. Safety Benefits

The construction of the diverging diamond interchanges and the upgrades to the intersections of Glenmore Trail with 100 Street SE, Rainbow Road, and Conrich Road are expected to improve safety in the following ways:

- Grade separation will reduce the number of at-grade intersections along Glenmore Trail.
- The twinning of Glenmore Trail reduces the risk of head-on collisions and improves the capacity of the roadway, which may reduce delays, stop-and-go traffic, and erratic driver behavior.
- Where provided, wide medians eliminate the fixed-object collision risk associated with a median barrier, and reduce the risk of head-on collisions.
- Wide shoulders and clear zones reduce the collision risk associated with run-off-road movements.
- The design of diverging diamond interchanges may result in several safety improvements, including:
 - A reduced number conflict points (14 instead of 32 for typical intersections and 26 for conventional diamond interchanges).
 - o Decreased stacking of vehicles making turning movements due to increased capacity.
 - o Conflict points spread out throughout interchange.
 - o Improved sight distance at turns.
 - Wrong way entry to ramps is difficult.
 - Pedestrian crossings are shorter.
 - Simplified signal phasing at intersections.
- All three diverging diamond interchanges proposed have a largely consistent design. This consistency will help improve driver expectation, thereby reducing the risk of driver confusion and related collision risks.



4.2. Summary of Potential Safety Issues Identified

A summary of the potential safety issues identified during the Road Safety Audit, along with the risk assessment ratings for each issue, is provided in Table 2. The identified safety issues, including potential mitigation strategies, are discussed in detail in Section 4.3.

SAFETY ISSUE			
ISSUE #	DESCRIPTION		
1	Lane Balance on WB Glenmore Trail	C - D	
2	Inadequate Weave and Decision Sight Distance	C - D	
3	Visibility of Traffic Lights at Terminal Intersections	C - D	
4	Offset Stop Lines	C - D	
5	Potential for Wrong-Way Movements	С	
6	Left-Turns Entering Exit Lane	С	
7 Lack of Pedestrian Facilities		С	
8	Lane Drops Obscured by Bridge	В	
9 Merge on a Horizontal Curve		В	
10	Pedestrian Crosswalks on High Speed Ramps	В	
11	Short Merge Lengths on Glenmore On-Ramps	В	
12	12 Limited Through Lane Storage Space		
13	Close Proximity of Exit Ramps	В	
14	Through Traffic May Enter Long Left-Turn Lanes	В	

Table 2: Summary of Potential Safety Issues



4.3. Potential Safety Issues

The potential safety issues identified during the Road Safety Audit, including recommended mitigation strategies, have been summarized in the following tables.

Issue 1	Lane Balance on WB Glenmore Trail		
Descriptionlanes, exit lanes and lane dro transitions from 5 > 4 > 3 > 5 >		erous lane drops and additions due to added ne number of lanes on WB Glenmore Trail 5 > 4 > 3. This could result in numerous lane bulence and the potential for sideswipe and	
Location(s)	WB Glenmore Trail.		
Drawing(s)	Plans: RP1, PP2, Conrich Interchange	, Rainbow Road Interchange	
	Expected Severity:	Property Damage Only - Minor Injury	
Risk Assessment	Expected Frequency:	> 5 per year	
	Risk Rating:	C- D	
Mitigation Suggestions	Merging the on-ramps upstream of Glenmore Trail such that there is one added la instead of two at each interchange could result in four core lanes along Glenmo Trail and reduce the amount of lane changing taking place.		



Issue 2	Inadequate Weave and Decision Sight Distance		
Description For the basket weave option at 100 Street SE, there is a very short weave for S WB and NB to Stoney Trail traffic. The short weaving distance may result sideswipe and rear-end collisions. The risk is amplified by the likely high travolumes (particularly trucks) and limited sight distance due to the horizontal curves on both approaches. Furthermore, there is not adequate distance to provinguidance (through guide signs) to motorists at the fork due to the close proximity 100 Street SE.			
Location(s)	Weaving section in northwest quadrant of 100 St	reet SE interchange.	
Drawing(s)	Weaving section in northwest quadrant of 100 Street SE interchange.		
Risk	Expected Severity:	PDO – Minor Injury	
Assessment	Expected Frequency:	> 5 per year	
	Risk Rating:	C - D	
 Mitigation Suggestions Increase the length of the weaving section Relocate the weave further west of intersection Consider alternate basket weave or interchange configuration 		section	



Issue 3	Visibility of Traffic Lights at Terminal Intersections		
Description	It is assumed that the ramp terminal intersections are signalized for the left-turns onto the cross-streets. The positioning of the signal heads may introduce driver confusion if the signals are visible to motorists travelling NB and SB. This may result in NB or SB traffic stopping when not required to do so, which could result in rear- end collisions. Due to the curvature of the ramp approaches, the signals may be difficult to see further in advance of the signal, which increases the risk that motorists will not see the signal (potential red light running) or will see the signal at the last second (sudden braking).		
Location(s)	All off-ramp terminal intersections	3.	
Drawing(s)	Plans: RP1, PP2, Conrich Interch	hange, Rainbow Road Interchange	
Risk	Expected Severity:	Minor Injury – Major Injury	
Assessment	Expected Frequency:	1 – 4 per year	
	Risk Rating:	C - D	
Mitigation Suggestions	 Optimize the angle of the traffic signal heads to maximize the sight distance for the vehicles on the ramp, while minimizing the visibility of the signal for through traffic. Provide lane designation signs over the signal heads. Provide a secondary signal that is visible further upstream on the ramps. 		



Issue 4	Offset Stop Lines		
Description	ersections at the 100 Street SE interchange s, may result in motorists in the left-hand lanes a lanes if the align with adjacent vehicles rather op bar is deteriorated or covered in snow. It is at developed at this stage and may not be the rs, but the comment is still provided for		
Location(s)	Stop bars at the cross-over intersection	ons at 100 Street SE	
Drawing(s)	(s)		
	Expected Severity:	Major Injury - Fatal	
Risk Assessment	Expected Frequency:	< 1 per year, > 1 per 5 years	
	Risk Rating:	C - D	
 Mitigation Suggestions Align stop bars with the stop bar furthest from the intersection. Ensure signal timings and clearance provide sufficient yellow and to clear the intersection. 			



Issue 5	Potential for Wrong-Way Movements		
Descriptionclosely with approach lanes at with lane designation and the lanes. This risk is increased giv on the right-hand side of the		ections is such that opposing traffic lanes align ersections. This may result in driver confusion ial for motorists to travel into oncoming traffic t driver expectations typically involve travelling As such, driver confusion at the cross-over neuvers, abrupt stopping and traffic blockages,	
Location(s)	Cross-over intersections at all interch	anges.	
Drawing(s)		e, Rainbow Road Interchange	
Risk	Expected Severity:	Major Injury	
Assessment	Expected Frequency:	< 1 per year, > 1 per 5 years	
	Risk Rating:	C	
Mitigation SuggestionsThis risk is common with diverging diamonds, particularly in area the configuration. The risk of wrong-way movements can be mitigat design stages through clear pavement markings (potentially include and signage, including "Do Not Enter" and "Turns Prohibited" signs		vay movements can be mitigated during future nt markings (potentially including leader lines)	



Issue 6	Left-Turns Entering Exit Lane		
Description	d dual left-turn lanes enter three northbound an exit lane to westbound Glenmore Trail. nto the lane nearest the left side of the road. the left-hand lane entering the exit lane. This g as motorists attempt to change lanes into e exit. As a result, there may be an increased hs. A similar issue exists with WB to SB left- ne.		
Location(s)	EB to NB and WB to SB left-turn lanes.		
Drawing(s)	EB to NB and WB to SB left-turn lanes.		
Pick	Expected Severity:	Property Damage Only	
Risk Assessment	Expected Frequency:	> 5 per year	
	Risk Rating:	С	
Mitigation Suggestions	The addition of leader line pavement markings and appropriate overhead guide signage may improve lane delineation and help guide motorists to turn into the appropriate travel lanes.		



Issue 7	Lack of Pedestrian Facilities		
Description	The drawings provided do not indicate any pedestrian or bicycle facilities at the Conrich Road or Rainbow Road interchanges. Although the interchanges will be in a predominantly industrial area, there still may be desire lines for crossing Glenmore Trail. Failure to provide facilities could result in pedestrians crossing or walking along Glenmore Trail or the cross-streets. Due to the vulnerability of pedestrians, any collisions have the potential to be severe.		
Location(s)	Conrich Road and Garden Road	Interchanges	
Drawing(s)	Plans: Conrich Interchange, Rain	bow Road Interchange	
	Expected Severity:	Fatal	
Risk Assessment	Expected Frequency: Risk Rating:	< 1 per 5 years C	
Mitigation Suggestions Provide pedestrian (and potentially bicycle) facilities on C Rainbow Road; or, • Provide multi-use trail overpasses over Glenmore Trail.			



Issue 8	Lane Drops Obscured	by Bridge
Description	Rainbow Road interchanges. Due they may be difficult for motorists including shadows and poor illum difficult to sign the location of the l a run-off-road incident. Lane dro	tere are lane drops under the Conrich Road and to the location of the lane drops under the bridge, s to identify due to obstructions from the bridge, ination. The bridge abutment may also make it ane drop and could pose a hazard in the event of ops under bridges are atypical and may not be is that are not aware of the lane drop might make road.
Location(s)	WB Glenmore Trail under Conrich	n Road and Rainbow Road
Drawing(s)	Plans: Conrich Interchange, Rain	<image/>
Diole	Expected Severity:	Minor Injury
Risk Assessment	Expected Frequency:	< 1 per year, > 1 per 5 years
	Risk Rating:	В
Mitigation Suggestions	 Relocate lane drop east of bridge structure See Issue 1 regarding suggestions for WB Glenmore laning 	



Issue 9	Merge on a Horizontal Cu	urve
Description	The right-turn from WB Glenmore Trail to NB 100 Street SE merges with NB traffic on a horizontal curve. WB-NB traffic must negotiate a series of reverse curves to complete the movement while at the same time trying to assess gaps in traffic and adjust their speed. Tracking the road alignment and gaps in traffic could be difficult and result in lane departures (sideswipe and run-off-road collision potential).	
Location(s)	WB Glenmore Trail to NB 100 Street S	SE
Drawing(s)	Plan: RP1, PP2	
	Expected Severity:	Property Damage Only
Risk Assessment	Expected Frequency:	1 – 4 per year
	Risk Rating:	В
Mitigation Suggestions	Consideration should be given to extending the merge lane to enter 100 Street SE on a tangent section north of the reverse curve to improve the visibility of the ending lane and vehicles in adjacent lanes.	



Issue 10	Pedestrian Crosswalks on High	Speed Ramps
Description	The pedestrian cross-walks on the NB to EB and SB to WB ramps at the 100 Street interchange are located mid way down the ramps. At this location, motorists may already be accelerating as they approach the mainline. Furthermore, they may not anticipate pedestrians so far down the ramp. Both of these factors may reduce motorists' ability to stop in the event of a pedestrian crossing.	
Location(s)	NB to EB and SB to WB ramps at the 100 Stree	t interchange.
Drawing(s)	RB to EB and SB to WB ramps at the 100 Street Interchange.	
	Expected Severity:	Major Injury
Risk Assessment	Expected Frequency:	< 1 per 5 years
	Risk Rating:	В
Mitigation Suggestions	Consider relocating the pedestrian crosswalks fu speed cross-street, where operating speeds are likely to anticipate pedestrians.	•



Issue 11	Short Merge Lengths on Glenm	ore On-Ramps
Description	At each interchange, the merge of the right-turn short considering the added complexities of the exit, free-flow left-turns and curvature of the ro factors result in a high workload for motorists wh speed and merge accordingly, increasing the collisions.	e curved approach for the left-turn bad at the merge location. These to may not have time to adjust their
Location(s)	All Glenmore Trail on-ramps	
Drawing(s)		
	Expected Severity:	Property Damage Only
Risk Assessment	Expected Frequency:	1 - 4 per year
	Risk Rating:	В
Mitigation Suggestions	 Extend the parallel section of the right-turn left-hand exit 	n lanes where they merge with the



Issue 12	Limited Through Lane Storage	Space	
Description	There is limited storage space available for NB through traffic on 100 Street at the north intersection. If the left-hand lane queue was to extend approximately 40m, it would block access to the right-hand NB-WB left-turn lane. In addition to operational issues, there is an increased risk for rear-end collisions for the back of the queue. Left-turn traffic in the middle lane may also make erratic lane changes to avoid the lane blockage, which could result in sideswipe collisions. This issue is not as pronounced in the SB direction or at the other two intersections, but it applies to both options at the 100 Street interchange.		
Location(s)	NB on 100 Street SE at the left-turn exit		
Drawing(s)	Plans: RP1, PP2		
Dial	Expected Severity:	Property Damage Only	
Risk Assessment	Expected Frequency:	1 – 4 per year	
	Risk Rating:	В	
Mitigation Suggestions	 Advance overhead signage could encourage through traffic to use the right- most lane. Review traffic model for likelihood of queue spillback. Consider timing revisions to minimize blockage. Consider storage extension if feasible. 		



Issue 13	Close Proximity of Exit Ramps		
Description	The exit ramps on westbound Glenmore Trail for 100 Street SE and Stoney Trail are in close proximity (380m) in the basket weave option. This limits the decision sight distance available to inform motorists of the exit locations. Providing adequate guide signage could be a challenge. With limited decision sight distance, there is an increased risk of erratic driver behaviors and abrupt lane changes that may potentially result in sideswipe and rear-end collisions.		
Location(s)	WB Glenmore Trail off-ramp to NB 100 Street SE and Stoney Trail.		
Drawing(s)		TAPER 25:1	
	Plan: RP1 Expected Severity:	Property Damage Only	
Risk Assessment	Expected Frequency:	1 – 4 per year	
	Risk Rating:	В	
Mitigation Suggestions	 Increase separation distance between in 	terchange off-ramps	



Issue 14	Through Traffic May Enter Long	g Left-Turn Lanes
Description	An additional left-turn lane is added on the no interchanges. The additional lane provides capa Glenmore Trail. The start of the left-turn lane intersection. Given the distance from the exit, th as an additional through lane, only to discover hand lanes. This could result in sudden or errat	city for traffic headed to westbound begins upstream of the preceding brough traffic may mistake the lane they need to get back to the right-
Location(s)	NB approach at 100 Street, Conrich Road, and I	Rainbow Road interchanges
Drawing(s)	Plans: RP1, PP2, Conrich Interchange, Rainbow	EB ON PAUP
	Expected Severity:	Property Damage Only
Risk Assessment	Expected Frequency:	1 – 4 per year B
	Risk Rating:	D
Mitigation Suggestions	Guide signs could be used to inform motorists consideration should be given to where those sig alignments could make it difficult for motorists to	ns can be placed as the curvilinear



5. Assumptions / Considerations

In addition to the issues detailed in the previous section, a number of considerations and assumptions were identified through the audit process as follows:

- Transitions at project limits on 100 Street SE are not shown and could not be assessed at this stage.
- A pedestrian pathway is shown to be constructed along the centre island of the diverging diamond interchange (along the east side of the northbound traffic lanes) at 100 Street SE. A physical separation should be provided between the traffic lane and the pedestrian pathway to provide a buffer for increased safety.
- The left-turn ramp terminal intersections from Glenmore Trail onto the northbound / southbound crossstreets were assumed to be signalized.

6. Conclusion

The proposed construction of the diverging diamond interchanges along Glenmore Trail SE at 100 Street SE, Conrich Road and Rainbow Road are expected to increase safety within the study area. Features of the road design that could be altered to further improve safety have been identified by this road safety audit, and are described in detail in Section 4.3.



Appendix A – Interchange Plan and Profile Drawing Package





DRAWING NUMBER	DRAWING TITLE	REVISION NO. & DATE	
		NO	YYYY-MM-DD
TI	TITLE PAGE		
DI	DRAWING INDEX		
PP1	GLENMORE TRAIL PLAN AND PROFILE		
PP2	GLENMORE TRAIL PLAN AND PROFILE		
PP3	GLENMORE TRAIL PLAN AND PROFILE		
PP4	GLENMORE TRAIL PLAN AND PROFILE		
IP1	INTERCHANGE PLAN - 100 STREET		
IP2	INTERCHANGE PLAN - CONRICH ROAD		
RP1	ROADWAY PLAN - BASKETWEAVE OPTION		
RP2	ROADWAY PLAN - BASKETWEAVE OPTION		
PR1	PROFILES - 100 ST. AND RAMPS		
PR2	PROFILES - 100 ST. AND RAMPS		
PR3	PROFILES - 100 ST. AND RAMPS		
PR4	PROFILES - BASKET WEAVE OPTION		
PR5	PROFILES - BASKET WEAVE OPTION		
PR6	PROFILES - CONRICH RD AND RAMPS		
PR7	PROFILES - CONRICH RD AND RAMPS		
PR8	PROFILES - CONRICH RD AND RAMPS		
TS1	TYPICAL SECTIONS		
TS2	TYPICAL SECTIONS		
ST1	STORMWATER PLAN		
ST2	STORMWATER PLAN		
ST3	STORMWATER PLAN		
ST4	STORMWATER PLAN		

CONSULTANT

PARSONS

LEGEND

ISL Engineering and Land Services


JOB No.

DRAWING NUMBER	DRAWING TITLE	REVISION NO. & DATE	
		NO	YYYY-MM-DD
B1	STRUCTURAL DRAWINGS		
B2	STRUCTURAL DRAWINGS		
B3	STRUCTURAL DRAWINGS		
B4	STRUCTURAL DRAWINGS		
B5	STRUCTURAL DRAWINGS		
B6	STRUCTURAL DRAWINGS		
B7	STRUCTURAL DRAWINGS		
U1	UTILITIES IMPACT PLAN		
U2	UTILITIES IMPACT PLAN		
U3	UTILITIES IMPACT PLAN		
U4	UTILITIES IMPACT PLAN		
WI	WETLAND IMPACT PLAN		
CS1	CONSTRUCTION STAGING PLAN - 100 ST.		
CS2	CONSTRUCTION STAGING PLAN - 100 ST.		
CS3	CONSTRUCTION STAGING PLAN - 100 ST.		
CS4	CONSTRUCTION STAGING PLAN - 100 ST.		
CS5	CONSTRUCTION STAGING PLAN - CONRICH RD.		
CS6	CONSTRUCTION STAGING PLAN - CONRICH RD.		
CS7	CONSTRUCTION STAGING PLAN - CONRICH RD.		
CS8	CONSTRUCTION STAGING PLAN - CONRICH RD.		
PA1	PROPERTY ACQUISITION PLAN		
PA2	PROPERTY ACQUISITION PLAN		
PA3	PROPERTY ACQUISITION PLAN		
PA4	PROPERTY ACQUISITION PLAN		

KEY PLAN		FUNCTIC GLENMORE TRAIL EAST - ST
	SCALE	PHOTOGRAPHY DATE


TIONAL PLANNING STUDY STONEY TR TO RAINBOW RD (RANGE ROAD 283) INDEX OF SHEETS





Calgary	1	
---------	---	--

HIGHWAY	DATE	SHEET	PLAN
560:02		1 OF 2	PP1



HIGHWAY	DATE	SHEET	PLAN
560:02		2 OF 2	PP2

