

Amenity ID	Component ID	Hierarchy Name	Description	Parent (Rollup To)	In-Service	Status	Location	Theoretical Useful Life (Years)	Inspection Date
					Date				
1389	A1030 - 1	A1030 - Slab on Grade	Reinforced Concrete Slab on Grade	A10 - Foundations	1977	In-service	Reinforced Concrete Slab on Grade	75	13-Sep-2018
1389	A2020 - 1	A2020 - Basement Walls	Foundation Walls	A20 - Basements	1977	In-service	Foundation Walls	75	13-Sep-2018
1389	B1010 - 1	B1010 - Floor Construction	Plywood Floor Sheathing, Open Web Steel Joist, Built Up Wood Beams	B10 - Super Structure	1977	In-service	Plywood Floor Sheathing, Open Web Steel Joist, Built Up Wood Beams	75	13-Sep-2018
1389	B1020 - 1	B1020 - Roof Construction	Wood Trusses	B10 - Super Structure	1977	In-service	Main Building	75	13-Sep-2018
1389	B2010 - 1	B2010 - Exterior Walls	East elevation siding deterioration	B20 - Exterior Enclosure	1977	In-service	Main Building	60	13-Sep-2018
1389	B2010 - 2	B2010 - Exterior Walls	Southeast stairwell investigation into bowing wall and water ingress	B20 - Exterior Enclosure	1977	In-service	Main Building: Southeast stairwell investigation into bowing wall and water ingress	60	13-Sep-2018
1389	B2020 - 1	B2020 - Exterior Windows	Metal clad wood-framed windows	B20 - Exterior Enclosure	1977	In-service	Main Building	35	13-Sep-2018
1389	B3010 - 1	B3010 - Roof Coverings	Roof gum cups and repairs	B30 - Roofing	2016	In-service	Main Building	20	13-Sep-2018
1389	C1010 - 1	C1010 - Partitions	Interior Partitions	C10 - Interior Construction	1977	In-service	Main Building: Interior Partitions	75	13-Sep-2018
1389	C1020 - 1	C1020 - Interior Doors	all Interior doors	C10 - Interior Construction	1977	In-service	Main Building	30	13-Sep-2018
1389	C1030 - 1	C1030 - Fittings	Washroom Stall Partitions	C10 - Interior Construction	1977	In-service	Main Building	30	13-Sep-2018
1389	C1030 - 2	C1030 - Fittings	Main Building: Kitchen Fittings	C10 - Interior Construction	1977	In-service	Main Building: Upper Kitchen	30	13-Sep-2018
1389	C1030 - 3	C1030 - Fittings	Lower Kitchen Fittings	C10 - Interior Construction	1977	In-service	Main Building: Lower Kitchen:	30	13-Sep-2018
1389	C1030 - 4	C1030 - Fittings	Vanity/Casework	C10 - Interior Construction	1977	In-service	Main Building: Upper Washroom	30	13-Sep-2018
1389	C1030 - 5	C1030 - Fittings	Washroom Accessories	C10 - Interior Construction	1977	In-service	Main Building: Upper Washroom	30	13-Sep-2018
1389	C1030 - 6	C1030 - Fittings	Washroom Accessories	C10 - Interior Construction	1977	In-service	Main Building: Lower Washroom	30	13-Sep-2018
1389	C3020 - 1	C3020 - Floor Finishes	VCT Flooring Study	C30 - Interior Finishes	2004	In-service	Main Building: VCT Flooring Study	25	13-Sep-2018
1389	C3020 - 2	C3020 - Floor Finishes	Main Building: Washroom Tiles	C30 - Interior Finishes	2004	In-service	Main Building: Washroom Tiles	30	13-Sep-2018
1389	D2010 - 1	D2010 - Plumbing Fixtures	Exterior Hose Bib	D20 - Plumbing	2005	In-service	Main Building - Exterior	30	13-Sep-2018
1389	D2010 - 2	D2010 - Plumbing Fixtures	Washrooms Water Closets	D20 - Plumbing	2005	In-service	Main Building - Washrooms	35	13-Sep-2018
1389	D2010 - 3	D2010 - Plumbing Fixtures	Men's First Floor Washroom Urinal	D20 - Plumbing	2005	In-service	Main Building - Men's First Floor Washroom	35	13-Sep-2018
1389	D2010 - 4	D2010 - Plumbing Fixtures	Washrooms Lavatory	D20 - Plumbing	2005	In-service	Main Building - Washrooms	35	13-Sep-2018

1389	D2010 - 5	D2010 - Plumbing Fixtures	Mechanical Room Service Sink	D20 - Plumbing	2005	In-service	Main Building - Mechanical Room	35	13-Sep-2018
1389	D2010 - 6	D2010 - Plumbing Fixtures	Basement Kitchen Stainless Steel Triple Compartment Sink	D20 - Plumbing	2005	In-service	Main Building - Basement Kitchen	35	13-Sep-2018
1389	D2010 - 7	D2010 - Plumbing Fixtures	Stainless Steel Single Compartment Sink	D20 - Plumbing	2005	In-service	Main Building - Main Floor Kitchen	35	13-Sep-2018
1389	D2010 - 8	D2010 - Plumbing Fixtures	Washrooms & Exterior Floor Drain	D20 - Plumbing	2005	In-service	Main Building - Washrooms & Exterior	50	13-Sep-2018
1389	D2020 - 1	D2020 - Domestic Water Distribution	Service Sink	D20 - Plumbing	2017	In-service	Main Building - Mechanical Room	20	13-Sep-2018
1389	D3010 - 1	D3010 - Energy Supply	Interior & Exterior Gas Line	D30 - HVAC	2017	In-service	Main Building - Interior & Exterior	50	13-Sep-2018
1389	D3020 - 1	D3020 - Heat Generating Systems	Lennox - Mechanical Room Furnace	D30 - HVAC	2018	In-service	Main Building - Lennox - Mechanical Room	25	13-Sep-2018
1389	D3040 - 1	D3040 - Distribution Systems	Greenshank Fan - Exterior Greenheck Exhaust Fan	D30 - HVAC	2017	In-service	Main Building - Greenshank Fan - Exterior	30	13-Sep-2018
1389	D3040 - 2	D3040 - Distribution Systems	Delhi Fan- Office Exhaust Fan	D30 - HVAC	2017	In-service	Main Building - Delhi Fan- Office	30	13-Sep-2018
1389	D3040 - 3	D3040 - Distribution Systems	York - Roof Rooftop Unit	D30 - HVAC	2017	In-service	Main Building - York - Roof	30	13-Sep-2018
1389	D3040 - 4	D3040 - Distribution Systems	Engineered Air - Roof Rooftop Unit	D30 - HVAC	2017	In-service	Main Building - Engineered Air - Roof	30	13-Sep-2018
1389	D4030 - 1	D4030 - Fire Protection Specialties	Interior Fire Extinguisher	D40 - Fire Protection	2017	In-service	Main Building - Interior	10	13-Sep-2018
1389	D5010 - 1	D5010 - Electrical Service & Distribution	Splitter- Square D Main Disconnect	D50 - Electrical	1976	In-service	Splitter Main Building, Square D	40	13-Sep-2018
1389	D5010 - 2	D5010 - Electrical Service & Distribution	Square D Panelboards A/B	D50 - Electrical	1976	In-service	Main Building Square D	40	13-Sep-2018
1389	D5020 - 1	D5020 - Lighting & Branch Wiring	T12 and Incandescent Lighting Interior Lighting	D50 - Electrical	1976	In-service	Main Building	40	13-Sep-2018
1389	G2020 - 1	G2020 - Parking Lots	Lot Grading and Drainage Parking Lot	G20 - Site Improvements	1976	In-service	Lot Grading and Drainage	50	13-Sep-2018